

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Photo # 3585 From entrance to location

Photo # 3586 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Jul 29, 2024 at 9:22:20 AM
CO



Jul 29, 2024 at 9:23:40 AM
CO

Photo # 3587 Location

Photo # 3588 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Photo # 3589 Location



Photo # 3590 Stored/unused piping on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Photo # 3591 Production tank capacity incorrect



Photo # 3592 Correct capacity

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Photo # 3593 Debris