

## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY T8-42 (J8E) Pad

Location #: 334821



Photo # 3887 From entrance to location




Photo # 3888 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY T8-42 (J8E) Pad

Location #: 334821



Photo # 3889 Location



Photo # 3890 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY T8-42 (J8E) Pad

Location #: 334821



Photo # 3891 Location



Photo # 3892 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY T8-42 (J8E) Pad

Location #: 334821



**Photo # 3893 Weeds in secondary containment**



**Photo # 3894 Weeds in secondary containment**