

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 37-33 Pad

Location ID: 335225



Photo # 4275 From entrance to location



Photo # 4276 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 37-33 Pad

Location ID: 335225



Photo # 4277 Location



Photo # 4278 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 37-33 Pad

Location ID: 335225



Photo # 4279 Location



Photo # 4280 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 37-33 Pad

Location ID: 335225



Photo # 4281 Burner exhaust stacks on separator unit lack bird protection



Photo # 4282 Burner exhaust stacks on separator unit lack bird protection

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 37-33 Pad

Location ID: 335225



Photo # 4283 Chemical tank label weathered & some required info is illegible/does not comply with CECMC rules