

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE RANCH RMV 104-33 Pad

Location ID: 323996



Photo # 4197 From entrance to location



Photo # 4198 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE RANCH RMV 104-33 Pad

Location ID: 323996



Jul 31, 2024 at 11:33:53 AM



Jul 31, 2024 at 11:33:26 AM

Photo # 4199 Location

Photo # 4200 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE RANCH RMV 104-33 Pad

Location ID: 323996



Photo # 4201 Location



Photo # 4202 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE RANCH RMV 104-33 Pad

Location ID: 323996



Photo # 4203 Open ended piping on separator unit/wildlife hazard



Photo # 4204 Open ended piping on separator unit/wildlife hazard