

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 43-28A Pad

Location ID: 323973



Photo # 4244 From entrance to location



Photo # 4245 Location

Location ID: 323973



Photo # 4247 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 43-28A Pad

Location ID: 323973




Photo # 4248 Location



Photo # 4249 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 43-28A Pad

Location ID: 323973



Jul 31, 2024 at 12:19:01 PM
CO

Photo # 4250 Open ended piping/wildlife hazard



Jul 31, 2024 at 12:19:10 PM
CO

Photo # 4251 Open ended piping/wildlife hazard



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources