

Inspection Photos

July 29th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325164

Inspection Document #: 714001019

La Plata County, CO

Township: NWNW 7 33N 11W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Long and Schluter 1
Location ID: 325164



7/29/24

+37.113611,-108.089763

46° NE



Photo 1. View of project area taken from the southern edge facing center.

Inspection Photos
Location Name: Long and Schluter 1
Location ID: 325164



Photo 2. View of the center part of the project area taken from the southern edge facing north. Note: Musk thistle observed in patches throughout the disturbance (indicated by red arrow).

Inspection Photos
Location Name: Long and Schluter 1
Location ID: 325164



Photo 3. Historical imagery from August 1, 1960 shows access road (indicated by red arrows) predates well/tank battery disturbance (high lighted in blue).