

Inspection Photos

July 29th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325311

Inspection Document #: 714001020

La Plata County, CO

Township: SESE 1 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Angelina-Menefee 1
Location ID: 325311



7/29/24
+37.124227,-108.090174
279° W

Photo 1. View of project area taken from the eastern edge facing west.

Inspection Photos
Location Name: Angelina-Menefee 1
Location ID: 325311



Photo 2. Cardinal photos taken from the center of the disturbance, left photo facing north, right photo facing east.

Inspection Photos
Location Name: Angelina-Menefee 1
Location ID: 325311



Photo 3. Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west. Note: project area appears consistent with adjacent reference area.

Inspection Photos
Location Name: Angelina-Menefee 1
Location ID: 325311



Photo 4. Reference area comprised of Broom snakeweed, Sagebrush and Curlycup gumweed.