

Inspection Photos

July 31st, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 313471

Inspection Document #: 714001024

Montezuma County, CO

Township: NWNW 13 38N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: McElmo Dome Unit 13-38-19 CA1

Location ID: 313471



7/31/24

+37.839737,-109.462326

185° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from northern edge facing south.

API #: 067-06201

Inspection Photos
Location Name: McElmo Dome Unit 13-38-19 CA1
Location ID: 313471



Photo 2. View of vegetation transects conducted in the project area (left) and within the reference area (right).

Inspection Photos

Location Name: McElmo Dome Unit 13-38-19 CA1

Location ID: 313471



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of spur access road running west to east to the project area from the main federal gravel road to the west.

API #: 067-06201

Inspection Photos

Location Name: McElmo Dome Unit 13-38-19 CA1

Location ID: 313471



7/31/24
+37.839737,-109.462326
169° S

Photo 4. Access road to the west of the project area has not been de-compacted, recontoured or reclaimed.

Inspection Photos

Location Name: McElmo Dome Unit 13-38-19 CA1

Location ID: 313471



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of the reference area comprised of Sagebrush, Juniper and Indian ricegrass.

API #: 067-06201