

Inspection Photos  
Location Name: FARM\_RANCH\_EXPLORATION\_FACILITY  
Location ID: 475504



Jul 24, 2024 at 12:55:45 PM  
N 39° 50' 0", W 104° 32' 11"  
280° V  
Adams County Inspection



Photo #1 Tanks, weeds throughout.

Photo #2 ECD and separator house.


## Inspection Photos

Location Name: FARM\_RANCH\_EXPLORATION\_FACILITY

Location ID: 475504



**Photo #3 Stained soil on back side of the separator.**



**Photo #4 ECD with 3 dead Kestrels 3 dead barn owls and one live barn owl.**

Inspection Photos  
Location Name: FARM\_RANCH\_EXPLORATION\_FACILITY  
Location ID: 475504



Photo #5 the living barn owl.

Photo #6 one of the 3 dead barn owls.

Inspection Photos  
Location Name: FARM\_RANCH\_EXPLORATION\_FACILITY  
Location ID: 475504



Photo #5 2 dead Kestrels.



Photo #6 1 dead Kestrel and 2 dead Barn owls.