

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403706748
Receive Date:
03/12/2024
Report taken by:
Kilian Collins

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC Operator No: 100322 Phone Numbers
Address: 1099 18TH STREET SUITE 1500 Phone: (970) 730-7281
City: DENVER State: CO Zip: 80202 Mobile: ()
Contact Person: Dan Peterson Email: RBUEUF27@chevron.com

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 30474 Initial Form 27 Document #: 403462830

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
[X] Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
Rule 913.g: Changes of Operator.
Rule 915.b: Request to leave elevated inorganics in situ.
Other:

SITE INFORMATION

No Multiple Facilities

Facility Type: WELL Facility ID: API #: 123-34394 County Name: WELD
Facility Name: NEI C18-32D Latitude: 40.311880 Longitude: -104.594850
** correct Lat/Long if needed: Latitude: Longitude:
QtrQtr: NESW Sec: 18 Twp: 4N Range: 64W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Grassland
Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Riverine 0.11mi SW, 0.11mi E
NA

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste Other E&P Waste Non-E&P Waste
- Produced Water Workover Fluids
- Oil Tank Bottoms
- Condensate Pigging Waste
- Drilling Fluids Rig Wash
- Drill Cuttings Spent Filters
- Pit Bottoms
- Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab analysis if encountered
Yes	SOILS	10' x 10' x 3' bgs	Lab analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a supplemental site investigation was conducted pertaining to the NEI C18-32D flowline abandonment. Approximately 246' of flowline was removed. Soil samples were taken along the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway. Soil screenings were also be taken along the flowline as appropriate. The Flowline Pre-Abandonment Notice Document number is included under Related Forms.

A sample was taken at the separator during decommissioning of the associated facility, please refer to REM #30380.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities. Additionally, soil samples were collected at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway. Soil samples were analyzed by a certified laboratory for the full extent of Table 915-1, including but not limited to: TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, metals, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during the site investigation a grab groundwater sample will be collected and analyzed for all organic compounds per COGCC Table 915-1.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

[Empty box for surface water sampling details]

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the flowline areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The ECMC Flowline Closure Checklist was utilized and filled out during the abandonment process. A photolog will be submitted on the Subsequent Form 27.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 1
Number of soil samples exceeding 915-1 1
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 100

NA / ND

ND Highest concentration of TPH (mg/kg) _____
-- Highest concentration of SAR 1
BTEX > 915-1 No
Vertical Extent > 915-1 (in feet) 3

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 915-1 _____

Highest concentration of Benzene (µg/l) _____
Highest concentration of Toluene (µg/l) _____
Highest concentration of Ethylbenzene (µg/l) _____
Highest concentration of Xylene (µg/l) _____
Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

Analytical soil samples will be collected at the direction change shown on the flowline site map (FL01-01), as well as at the wellhead riser end of the flowline (FL01R-W) which will be collected for full Table 915-1 analysis. Concurrently with the flowline sampling, background samples will be collected for analysis of metals in soil per ECMC Table 915-1, pH, SAR, EC, and boron. A proposal to collect additional background samples adjacent to the flowline was submitted under ECMC document #403606398 for the NEI C18-21D flowline. So as to not duplicate background sampling efforts, proposed background soil samples are not shown on the map attached to this Form 27 for the NEI C18-20D. All proposed flowline sample locations were selected based on the approved sampling map attached to the Form 27 Initial (ECMC Document #403462830). The results of the flowline decommissioning and background sampling will be submitted on a subsequent Form 27.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Refer to Remediation Summary section below.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A supplemental site investigation will be completed in accordance with the attached proposed site investigation map, and proposed sampling plan outlined in the Site Investigation Report section of this Form 27.

Soil Remediation Summary

In Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

Ex Situ

- _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____
- _____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Supplemental Site Investigation Report

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 09/14/2023

Proposed date of completion of Reclamation. 11/21/2025

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 05/11/2023

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 09/14/2023

Proposed site investigation commencement. 05/24/2024

Proposed completion of site investigation. 11/22/2024

REMEDIAL ACTION DATES

Proposed start date of Remediation. 11/22/2024

Proposed date of completion of Remediation. 11/21/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

Proposed completion of remediation date is being updated to reflect the schedule to complete the remedial excavation. The ECMC will be updated on a subsequent Form 27 with the results of the remedial excavation, or if the schedule is changed due to site access constraints.

OPERATOR COMMENT

This Form 27 is being submitted to include the decommissioning results for the NEI C18-32D Flowline. A proposal to collect additional flowline samples is presented in the Site Investigation Report section of this Form 27. The results of the supplemental site investigation will be submitted on a subsequent Form 27.

A proposal to collect additional background samples adjacent to the flowline was submitted under ECMC document #403606398 for the NEI C18-21D flowline. So as to not duplicate background sampling efforts, proposed background soil samples are not shown on the map attached to this Form 27 for the NEI C18-20D.

The Site Map attached to the Form 27 Initial (ECMC Document Number 403462830) included one Soil Sample Location on the east side of separator at the associated Tank Battery. This separator flowline riser sample was not collected during the flowline decommissioning completed on September 14, 2023. However, the separator flowline riser was sampled during the NEI C18-32D Tank Battery Decommissioning (Remediation #30380). The separator flowline riser SEP01-FL@2' (40.31184432, -104.59572132) was sampled during the NEI C18-32D Tank Battery Decommissioning (Remediation #30380) on September 14, 2023.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Allan Engelhardt

Title: Environmental Consultant

Submit Date: 03/12/2024

Email: chevroneform@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Kilian Collins

Date: 08/06/2024

Remediation Project Number: 30474

COA Type

Description

	Operator shall maintain a quarterly reporting schedule and submit a Supplemental Form 27 with an updated Implementation Schedule at least 14 days in advance of any changes per Rule 913.d.(2).
	Operator states "A sample was taken at the separator during decommissioning of the associated facility, please refer to REM #30380." and "A proposal to collect additional background samples adjacent to the flowline was submitted under ECMC document #403606398 for the NEI C18-21D flowline." Any data intended to be utilized for closure of this remediation project must be presented to this remediation project number.
2 COAs	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

<u>Att Doc Num</u>	<u>Name</u>
403706748	FORM 27-SUPPLEMENTAL-SUBMITTED
403803774	SITE INVESTIGATION REPORT
403804604	SITE INVESTIGATION PLAN

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	Operator makes reference in basis for change of implementation schedule to a remedial excavation at this site, but that is not reflected in the Remedial Action Plan or Site Investigation Report.	08/05/2024

Total: 1 comment(s)