

Inspection Photos
Location Name: CORNISH-66N63W/8SWSW
Location ID: 306191



Photo #1
Cornish 14-8 (123-24168) Wellsite
Producing | PR



Photo #2
Cornish 14-8 Battery site
Active
Equipment Documented; Loc ID: 306191



Inspection Photos

Location Name: CORNISH-66N63W/8SWSW

Location ID: 306191



Photo #3

Cornish 14-8 Battery site

Active

Well / Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources