

COLORADO OIL AND GAS CONSERVATION COMMISSION
Room 721, State Centennial Building
1313 Sherman Street
Denver, Colorado 80203



WELL SITE INSPECTION

Date: 6/26/84

Field: Cedar Creek Operator: Getty Oil

Well Name: G. A. Henderson #6

Location: NESW Sec 18 Twp 9N Rng 53W

Injection Zone: J

Well Type: ☒ Tubing-packer
☐ Casing Disposal
☐ Dual completion

Status at time of inspection:

☐ Injecting
☐ Not Injecting

Remarks: _____

Injection Pressure 0 psi

Tubing-Casing Annulus Pressure 300 psi

If Annulus pressure released, time it took
to bleed down _____

Remarks: witness Mit, tried to
pressure annulus, pumped
approx 50 bbl. had
communication with
tubing possible tubing
or packer leak. will
fix

Failed test - will retest

