

WELL NAME: MARTINEZ 43-20, API #: 071-06359, INSP. # 695110108



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION




PHOTO 3: WELLHEAD AND EQUIPMENT



PHOTO 4: UNUSED EQUIPMENT (1" RISER WEST OF WELLHEAD). REMOVE OR MARK UNUSED RISER PER RULE 606. CA DATE 9-6-2024.





PHOTO 5: UNUSED EQUIPMENT (1" RISER NORTH OF WELLHEAD). REMOVE OR MARK UNUSED RISER PER RULE 606. CA DATE 9-6-2024.



PHOTO 6: AREA OF IMPACTED SOIL AROUND COMPRESSOR PRIME MOVER. REVIEW Self-inspection, maintenance, and good housekeeping procedures and schedules, REMOVE OR TREAT IMPACTED MATERIAL AND REPAIR LEAKING EQUIPMENT BEFORE PUTTING BACK ON LINE PER RULE 1002..(2).D. CA DATE 9-6-2024.



PHOTO 7: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. REVIEW Self-inspection, maintenance, and good housekeeping procedures and schedules, REMOVE OR TREAT IMPACTED MATERIAL AND REPAIR LEAKING EQUIPMENT BEFORE PUTTING BACK ON LINE PER RULE 1002..(2).D. CA DATE 9-6-2024.