

Inspection Photos
Location Name: Klein-62N62W 9NWSE Tank Battery
Location ID: 318289



Tank Battery & Overgrown Vegetation



Inspection Photos
Location Name: Klein-62N62W 9NWSE Tank Battery
Location ID: 318289



Overgrown Vegetation



Overgrown Vegetation

Inspection Photos

Location Name: Klein-62N62W 9NWSE Tank Battery

Location ID: 318289



Missing Capacity Label



Gas Meter Run

Inspection Photos

Location Name: Klein-62N62W 9NWSE Tank Battery

Location ID: 318289



Separator & Overgrown Vegetation



Separator & Overgrown Vegetation

