

Inspection Photos

Location Name: Klein-62N62W 8NENW Tank Battery

Location ID: 318664



Location & Overgrown Vegetation



Separator & Overgrown Vegetation

Inspection Photos

Location Name: Klein-62N62W 8NENW Tank Battery

Location ID: 318664



Production tank needs capacity label & Overgrown Vegetation

Pit is missing capacity label & Overgrown Vegetation