

Inspection Photos

Loc: 322263

Operator: **JAVERNICK OIL**

Inspection Date: 8/5/2024

County: **FREMONT**



Inspection Photos



Photo 3. Facing southwest at the abandoned wellsite. There is a pipe at red arrow and wood block. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322263 | Date: 8/5/2024

Inspection Photos



Photo 2. The hardened oil stained soil still remains and was not cleaned up.

