



WELL SITE INSPECTION FORM

Well Name Mayberry #3 API Number 05 - 009 - 6379-1
Operator Midwestern Expt. Permit # _____
Location SWNE 10 - 345 41 County Balg
Field Greenwood Inspector EBB

Bond = CD\$5000

AL/PA/DA Inspection Results:

Well Status: RC

Pass(Y) _____ Fail(N) _____ Date _____ ND _____ DG _____ WO X PR _____ SI _____ TA _____

=====

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____

Consistent with APD casing Program? YES _____ NO _____ Returns _____

Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion 1-29-92

Prod. Csg. Set? yes Completion Rig/Activity ✓

Drilling Pits: Closed _____ Open ✓ Wellhead Installed: valve Sign: Yes _____ No X

Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: ✓ Prod. Tanks: (4) 300 BBLs

Equipment flow line to lease Meter Run: Yes _____ No X

Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. e

gas supply to lease

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____

Hole Plugged: Yes _____ No _____ Pits Backfilled: Yes _____ No _____

Material Buried: Yes _____ No _____ N/A _____ Site Clean: Yes _____ No _____

Bond Release OK: Yes _____ No _____ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection _____

Comments: Common battery 4-300 #1 well = Jack

Free Water KO

2006 film skin

VHT

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____