

Inspection Photos

08/06/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312508

Inspection Doc: 696206084

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312508



Photo 1: Photos taken from the north end of the Location. Photo provides an overview of the Location facing southeast and southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312508



August 6, 2024



August 6, 2024

Photo 2: Photos 2-3 taken from central areas of the Location. Photo example showing areas on the Location that do not appear to have achieved a uniform desirable perennial vegetative establishment. Gravel material is apparent and appears to be hindering uniform establishment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312508



August 6, 2024

Photo 3: See comments under photo 2. Vegetation observed predominantly Undesirable Species, or biennial Sweetclover.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312508



Photo 4: Photo from the 11/24/2020 inspection. Photo shows cut slopes on the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312508



Photo 5: Continued from photo 4. Photo example showing cut slopes remain relatively unchanged and predominantly bare.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312508



Photo 6: Photos 6-7 taken along the access road leading to the Location. Photos show gravel material has not been placed along the road per Form 4 COAs.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312508



Photo 7: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312508

August 6, 2024



August 6, 2024



Photo 8: Photos taken from the access gate. Photo shows Operator's lock has been cut and no longer functional.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources