

Inspection Photos

Location: Caerus Piceance LLC Keinath-67S96W/33SESE

Location ID: 334137

Date: 8/6/2024



Entrance to location - Photo #04241



Location - Photo #04246

Inspection Photos

Location: Caerus Piceance LLC Keinath-67S96W/33SESE

Location ID: 334137

Date: 8/6/2024



Wellhead - Photo #04242



Stockpiled soils with no BMP's - Photo #04277