

Inspection Photos

Location Name: Cooper-62N62W 20SENE Tank Battery

Location ID: 318519



Location & Overgrown Vegetation

Tank Battery & Overgrown Vegetation

Inspection Photos

Location Name: Cooper-62N62W 20SENE Tank Battery

Location ID: 318519



Overgrown Vegetation

Overgrown Vegetation

Inspection Photos

Location Name: Cooper-62N62W 20SENE Tank Battery

Location ID: 318519



Separator & Overgrown Vegetation

Gas Meter Run & Overgrown Vegetation