

# Inspection Photos

July 31st, 2024

Operator: Seeley Oil Company - 10506

Location ID: 313581

Inspection Document #: 714001035

Montezuma County, CO

Township: SESW 35 37N 19W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Cutthroat 14  
Location ID: 313581

7/31/24  
+37.839737,-109.462326  
156° SE



**Photo 1.** View of the well pad taken from the access point facing center.



Inspection Photos  
Location Name: Cutthroat 14  
Location ID: 313581

7/31/24  
+37.839737,-109.462326  
114° SE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the southern interim reclamation area facing southeast.

API #: 083-06595



Inspection Photos  
Location Name: Cutthroat 14  
Location ID: 313581

7/31/24  
+37.416796,-108.913923  
282° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Reference area comprised of Big sagebrush, Juniper and Ephedra.

API #: 083-06595