

Inspection Photos

July 31st, 2024

Operator: Seeley Oil Company - 10506

Location ID: 313578

Inspection Document #: 714001036

Montezuma County, CO

Township: SWNE 35 37N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cutthroat 12
Location ID: 313578

7/31/24
+37.423746,-108.910617
172° S



Photo 1. View of the well pad taken from the access point facing center.



Inspection Photos
Location Name: Cutthroat 12
Location ID: 313578



Inspection Photos
Location Name: Cutthroat 12
Location ID: 313578



Inspection Photos
Location Name: Cutthroat 12
Location ID: 313578

7/31/24
+37.423311,-108.910620
174° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of the western interim reclamation area facing south.

API #: 083-06591

Inspection Photos
Location Name: Cutthroat 12
Location ID: 313578

7/31/24
+37.416796,-108.913923
282° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area comprised of Big sagebrush, Juniper and Ephedra.

API #: 083-06591