

Inspection Photos

July 31st, 2024

Operator: Seeley Oil Company - 10506

Location ID: 313548

Inspection Document #: 714001038

Montezuma County, CO

Township: SWNE 26 37N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cutthroat 5
Location ID: 313548

7/31/24
+37.436694,-108.910964
336° NW



Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Cutthroat 5
Location ID: 313548

7/31/24
+37.437009,-108.910244
97° E



Photo 2. View of weedy debris in the produced water/crude oil secondary containment.

Inspection Photos
Location Name: Cutthroat 5
Location ID: 313548

7/31/24
+37-437088,-108.910153
110° E



Photo 3. View of produced water and crude oil tank labels that are not reflecting current operator.

Inspection Photos
Location Name: Cutthroat 5
Location ID: 313548

7/31/24
+37.436828,-108.910533
179° S



Photo 4. View of the eastern interim reclamation area facing south.



Inspection Photos
Location Name: Cutthroat 5
Location ID: 313548

7/31/24
+37.416796,-108.913923
282° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of Big sagebrush, Juniper and Ephedra.

API #: 083-06496