

Inspection Photos

July 31st, 2024

Operator: Seeley Oil Company - 10506

Location ID: 313536

Inspection Document #: 714001039

Montezuma County, CO

Township: SESW 23 37N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cutthroat 3
Location ID: 313536

7/31/24
+37.443855,-108.914926
337° NW



Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Cutthroat 3
Location ID: 313536

7/31/24
+37.443958,-108.914904
15° N



Photo 2. View of the eastern interim reclamation area facing north.

Inspection Photos
Location Name: Cutthroat 3
Location ID: 313536

7/31/24
+37.416796,-108.913923
282° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area comprised of Big sagebrush, Juniper and Ephedra.

API #: 083-06446