

Inspection Photos

August 6th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333432

Inspection Document #: 714001043

La Plata County, CO

Township: SWNW 26 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cugnini A1, A3
Location ID: 333432

8/6/24
+37.165568,-107.802363
135° SE



Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Cugnini A1, A3
Location ID: 333432



Photo 2. Stormwater corrective action identified in the previous inspection doc #714000258 has been addressed/resolved.

Inspection Photos
Location Name: Cugnini A1, A3
Location ID: 333432



Photo 3. Large patches of Musk and Canada thistle observed flowering throughout the location. More patches of thistle not pictured observed throughout the location.

Inspection Photos
Location Name: Cugnini A1, A3
Location ID: 333432



Photo 4. Weedy debris corrective action identified in the previous inspection doc #714000258 has been addressed/resolved.

Inspection Photos
Location Name: Cugnini A1, A3
Location ID: 333432



8/6/24
+37.165479,-107.802522
231° SW



Photo 5. Reference area of grass agricultural field.