

Interim Reclamation and Stormwater Inspection

Date: 8/6/24

Operator: PDC Energy Inc - 69175

Location ID: 332604

Inspection Document #: 713900834

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN

SUGAR-64N67W 9NENW

Location ID: 332604



Photo 1. The photo was taken at the entrance to the well location facing Southwest. The photo illustrates Operator sign needs replaced.

Photo 2. The photo was taken at the tank battery location facing Northeast. The photo illustrates erosion on the production pad.

Inspection Photos

Location Name: GREAT WESTERN

SUGAR-64N67W 9NENW

Location ID: 332604



Photo 3. The photo was taken at the tank battery location facing West. The photo illustrates trash and musk thistle on the west side of the tank battery location interim area.



Photo 4. The photo was taken at the tank battery location facing North. The photo illustrates unmanaged kochia on production pad.

Inspection Photos

Location Name: GREAT WESTERN

SUGAR-64N67W 9NENW

Location ID: 332604



Photo 5. The photo was taken at the well location facing South. The photo illustrates unmanaged kochia around the wellhead area.



Photo 6. The photo was taken at the well location facing East. The photo illustrates trash on the East side of the location.