

# Final Reclamation and Stormwater Inspection

Date: 8/6/24

Operator: Mountain Petroleum Corp - 60890

Location ID: 410610

Inspection Document #: 713900838

Yuma County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Blach #2-19  
Location ID: 410610



**Photo 1.** The photo was taken South of the well location facing North. The photo illustrates a large area of bare soil where the former wellhead was located, with approximately a 10' radius.

**Photo 2.** The photo was taken West of the well location facing East. Refer to the comment for photo 1.

Inspection Photos  
Location Name: Blach #2-19  
Location ID: 410610



**Photo 3.** The photo was taken North of the well location facing South. Refer to the comment for photo 1.

**Photo 4.** The photo was taken East of the well location facing West. Refer to the comment for photo 1.

Inspection Photos  
Location Name: Blach #2-19  
Location ID: 410610



**Photo 5.** The photo was taken at the tank battery location facing North. The photo illustrates bare soil is predominant on the location.

**Photo 6.** The photo was taken at the tank battery location facing East. Refer to the comment for photo 5.

Inspection Photos  
Location Name: Blach #2-19  
Location ID: 410610



**Photo 7.** The photo was taken at the tank battery location facing South. Refer to the comment for photo 5.



**Photo 8.** The photo was taken at the tank battery location facing West. Refer to the comment for photo 5.

Inspection Photos  
Location Name: Blach #2-19  
Location ID: 410610



**Photo 9.** The photo was taken at the tank battery location facing West. The photo illustrates a large area of bare soil at the location.



**Photo 10.** The reference photo was taken North of the location facing Northeast.