


Operator: HPR


Location Name: Randall Creek 13-27H

Loc ID: 424282

Inspection: 696300679



Randall Creek 13-27H
23 Jul 2024, 3:49:34 PM



Randall Creek 13-27H
22 Jul 2024, 1:33:21 PM

CA: Stained soil at Wellhead, see photo 3. Corrective Action: Comply with Rule 907.e

CA Resolution: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.

CA: Northeast Deadman Anchor is not marked, see photo 4. Corrective Action: Mark guy line anchors per Rule 604.c.(2)Q.

CA Resolution: Operator has provided follow-up to show that identified deadman has removed.