


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 125-33 Pad

Location ID: 334923



**Photo # 5004 From entrance to location**



**Photo # 5005 Location**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 125-33 Pad

Location ID: 334923



Photo # 5006 Stored farm equipment in the interim area



Photo # 5007 Stored truck in the interim area



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 125-33 Pad

Location ID: 334923



Photo # 5008 Stored concrete slabs in the interim area



Photo # 5009 Stored concrete light bases in the interim area



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 125-33 Pad

Location ID: 334923



Photo # 5010 Unmarked deadman



Photo # 5011 Same unmarked deadman



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 125-33 Pad

Location ID: 334923



Photo # 5012 Unmarked deadman



Photo # 5013 Same unmarked deadman



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 125-33 Pad

Location ID: 334923



Photo # 5014 Unmarked deadman



Photo # 5015 Same unmarked deadman

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 125-33 Pad

Location ID: 334923



**Photo # 5016 Some required info on chemical tank label is illegible/does not comply with CECMC labeling rules**