

Final Reclamation and Stormwater Inspection

Date: 8/6/24

Operator: Foundation Energy Management LLC -
10112

Location ID: 303030

Inspection Document #: 713900840

Yuma County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Blach #1-24
Location ID: 303030



Photo 1. The photo was taken at the well location facing Southwest. The photo illustrates the former area of the tank battery and well is now an area of bare soil that appears to have ponded in the past based on observations on the ground and with imagery.

Photo 2. The photo was taken at the well location facing West. Refer to the comment for photo 1.

Inspection Photos
Location Name: Blach #1-24
Location ID: 303030



Photo 3. The photo was taken at the well location facing East. Refer to the comment for photo 1.



Photo 4. The photo was taken at the well location facing South. Refer to the comment for photo 1.

Inspection Photos
Location Name: Blach #1-24
Location ID: 303030



Photo 5. The photo was taken East of the well location facing North. The photo illustrates the area has been grazed and the area is used heavily by cattle because of the nearby water tank.

Photo 6. The reference photo was taken South of the well location facing South.

Inspection Photos
Location Name: Blach #1-24
Location ID: 303030



Photo 7. The photo is of Google Earth imagery from 8/11/2022. The image illustrates the location of the former well is now a large bare area of soil.

Inspection Photos
Location Name: Blach #1-24
Location ID: 303030



Photo 8. The photo is of Google Earth imagery from 3/19/2016. The image illustrates the former well and tank battery location.