

# Inspection Photos

API: 011-05057

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 8/7/2024

County: Prowers



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone photo (taken on 5/8/24) facing down toward the wellsite. There is an area with no vegetation which appears impacted soil from a historical spill.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 011-05057 | Date: 8/7/2024



## Inspection Photos



**Photo 2.** Facing northeast toward the wellsite.



## Inspection Photos



**Photo 3.** There is concrete debris and unused pipe that needs to be removed..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API: 011-05057 | Date: 8/7/2024



## Inspection Photos



**Photo 4.** Northeast corner of the location. There is part of a metal shed and unused pipe that needs to be removed.

