

Inspection Photos

08/06/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334411

Inspection Doc: 696206098

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334411



Photo 1: Photos 1-2 taken from the Location. Photos provide an overview from north, east, south and west. Location has achieved a uniform, 80% perennial vegetative cover to that of the adjacent reference.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334411



August 6, 2024



August 6, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334411



Photo 3: Photos taken from the north end of the Location. Photo shows concrete debris improperly stored on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources