

Operator: 8 North

Location Name: COX 1161-34-42

Loc ID: 415946

Inspection: 696301286



Exhibit A




Exhibit B




Exhibit C

CA: Unused to Stand, Containment and Wellhead parts, see photos. Corrective Action: Comply with Rule 603.f.

CA Resolution: Operator has appropriately removed identified unused equipment from location to comply with the 600 series.




Exhibit A

CA: Stained Soil at Exhaust, see photos Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

CA Resolution: Operator has properly disposed of the oily waste in accordance with 907.e.