

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403873927

Date Received:

08/01/2024

Spill report taken by:

Sanchez, Chris

Spill/Release Point ID:

487527

### SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

#### OPERATOR INFORMATION

Name of Operator: <u>MURFIN DRILLING COMPANY INC</u>	Operator No: <u>61650</u>	<b>Phone Numbers</b>
Address: <u>250 N WATER ST STE 300</u>		Phone: <u>(316) 858-8664</u>
City: <u>WICHITA</u> State: <u>KS</u> Zip: <u>67202</u>		Mobile: <u>( )</u>
Contact Person: <u>Cristina Goodrich</u>		Email: <u>cgoodrich@murfininc.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

#### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403873927

Initial Report Date: 08/01/2024 Date of Discovery: 07/29/2024 Spill Type: Historical Release

#### Spill/Release Point Location:

QTRQTR SESE SEC 34 TWP 34s RNG 46w MERIDIAN 6

Latitude: 37.034540 Longitude: -102.581378

Municipality (if within municipal boundaries): \_\_\_\_\_ County: BACA

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

#### Reference Location:

Facility Type: WELL

Facility/Location ID No \_\_\_\_\_

Spill/Release Point Name: SE Campo Unit 101

Well API No. (Only if the reference facility is well) 05-009-06440

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: historical unknown

Has the subject Spill/Release been controlled at the time of reporting? Yes

**Land Use:**

Current Land Use: NON-CROP LAND Other(Specify): rangeland

Weather Condition: sunny

Surface Owner: FEDERAL Other(Specify): USFS

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Laboratory results from soil sampling related to the plugged wellhead cut & cap initial assessment at the SE Campo Unit 101 indicate the floor soil sample collected adjacent to the cut & capped injection well contains concentrations of TPH DRO and RRO above ECMC's Table 915-1 limit. There is no threat to the public or environment.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
7/29/2024	United States Forest Service	Cullen LaPointe	-	email
7/29/2024	Colorado Parks & Wildlife	Cassidy English	-	email
7/29/2024	Colorado Parks & Wildlife	Karen Voltura	-	email
7/29/2024	Baca County OEM	Jennifer Leathers	-	email
7/29/2024	Baca County Assessor	Gayla Thompson	-	email
7/29/2024	ECMC	Chris Sanchez	-	email

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
 Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
 Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
 Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
 Was there damage during excavation? \_\_\_\_\_  
 Was CO 811 notified prior to excavation? \_\_\_\_\_

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

The presence of free product or hydrocarbon sheen Surface Water

The presence of free product or hydrocarbon sheen on Groundwater

The presence of contaminated soil in contact with Groundwater

The presence of contaminated soil in contact with Surface water

Yes Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.

No Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.

Areas offsite of Oil & Gas Location  Off-Location Flowline right of way

No Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.

No Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1 Supplemental Report Date: 08/01/2024

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	_____	_____	<input checked="" type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	_____	_____	<input checked="" type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply)  Soil  Groundwater  Surface Water  Dry Drainage Feature

Surface Area Impacted: \_\_\_\_\_ Length of Impact (feet): 1 Width of Impact (feet): 1

Depth of Impact (feet BGS): 1 Depth of Impact (inches BGS): \_\_\_\_\_

How was extent determined?

Extent has not yet been determined. Excavation for offsite disposal and confirmation sampling to be conducted.

Soil/Geology Description:

Otero sandy loam, 3 to 9% slopes

Depth to Groundwater (feet BGS) 95 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest

Water Well	<u>2980</u>	None <input type="checkbox"/>	Surface Water	<u>2535</u>	None <input type="checkbox"/>
Wetlands	_____	None <input checked="" type="checkbox"/>	Springs	_____	None <input checked="" type="checkbox"/>
Livestock	_____	None <input checked="" type="checkbox"/>	Occupied Building	_____	None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 08/01/2024

Root Cause of Spill/Release Unknown (Historical)

Other (specify) \_\_\_\_\_

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

wellhead

Describe Incident & Root Cause (include specific equipment and point of failure)

Laboratory results from soil sampling related to the plugged wellhead cut & cap initial assessment at the SE Campo Unit 101 indicate the floor soil sample collected adjacent to the cut & capped injection well contains concentrations of TPH DRO and RRO above ECMC's Table 915-1 limit. There is no threat to the public or environment.

Describe measures taken to prevent the problem(s) from reoccurring:

Well has been plugged and abandoned

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment  
 Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure:  Corrective Actions Completed (documentation attached, check all that apply)

Horizontal and Vertical extents of impacts have been delineated.

Documentation of compliance with Table 915-1 is attached.

All E&P Waste has been properly treated or disposed.

Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: 34358

SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

## OPERATOR COMMENTS:

Water well documents available on Colorado Division of Water Resources online database for water well receipt number 9072880 approximately 2,980' SW from the wellhead state a static groundwater level of 95' bgs. Per ECMC Rule 915.a., operators will adhere to the concentrations for soil cleanup in Table 915-1. Operators will use Residential Soil Screening Level Concentrations as cleanup levels.

Murfin would like to request a reduced analysis of TPH DRO & RRO, pH, and SAR only for wellhead excavation confirmation soil samples going forward.

On 7/25/24, the surface owner, the United States Forest Service, requested that Murfin withhold all dirt work and excavation in the Campo Field until further notice while they review previous archeological surveys.

See attached site investigation report for all figures, tables, photos, closure checklists, and laboratory analytical reports to-date.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: David Castro

Title: Senior Project Scientist Date: 08/01/2024 Email: dcastro@eagle-enviro.com

<b>COA Type</b>	<b>Description</b>
	ECMC approves the Operators request for a; reduced analysis of TPH DRO & RRO, pH, and SAR for the wellhead excavation.
	The impacted soil will be segregated for proper offsite disposal and the lateral and vertical extent of impacts shall be determined with appropriate confirmation soil sampling.
	Closure request is granted, Spill Remediation will proceed under Remediation # 34358. Operator shall provide Quarterly Updates for Remediation Project. All previously assigned COAs shall apply to Remediation # 34358
	Upon approval of this Form 19 the Operator shall update the Implementation Schedule for Spill/Remediation Project # 34358 through a Supplemental Form 27
4 COAs	

**ATTACHMENT LIST**

<b>Att Doc Num</b>	<b>Name</b>
403873927	SPILL/RELEASE REPORT(I/S)
403873994	ANALYTICAL RESULTS
403883134	FORM 19 SUBMITTED

Total Attach: 3 Files

**General Comments**

<b>User Group</b>	<b>Comment</b>	<b>Comment Date</b>
		Stamp Upon Approval

Total: 0 comment(s)