

Final Reclamation and Stormwater Inspection

Date: 08/06/2024

Operator: PDC ENERGY INC - 69175

Location ID: 306705

Inspection Document #: 708201484

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Rothe 24-29U
Location ID: 306705



Photo 1. The well location (Location ID 306705 with API 123-25137) meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. Well location and access road appear reflective of reference crop areas.

Inspection Photos
Location Name: Rothe 24-29U
Location ID: 306705



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Rothe 24-29U
Location ID: 306705



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: Rothe 24-29U
Location ID: 306705



Photo 4. Facing west; see comments in Photo 1.

Inspection Photos
Location Name: Rothe 24-29U
Location ID: 306705



Photo 5. Approximate well location; ground view.

Inspection Photos
Location Name: Rothe 24-29U
Location ID: 306705




Photo 6. Red line illustrates off-location flowline from the subject well (API 123-25137) to the associated tank battery. Operator is required to submit a Form 44 Off-Location Flowline Abandonment Notice per Rule 1105.f.(2).