

Inspection Photos


Location: Laramie Energy LLC CC/0605-01 Pad

Location ID: 323903

Date: 7/25/2024




Entrance to location - Photo #03599



Location - Photo #03617

Inspection Photos
Location: Laramie Energy LLC CC/0605-01 Pad
Location ID: 323903
Date: 7/25/2024



Wellhead - Photo #03600



Separator/Dehydrator - Photo #03602

Inspection Photos

Location: Laramie Energy LLC CC/0605-01 Pad

Location ID: 323903

Date: 7/25/2024



Jul 25, 2024 at 11:54:40 AM
+39.556441,-108.247523 ±3.54m

Tank battery - Photo #03616



Jul 25, 2024 at 12:12:16 PM
+39.555696,-108.247710 ±4.71m

Southeast corner of location - Photo #03630

Inspection Photos

Location: Laramie Energy LLC CC/0605-01 Pad

Location ID: 323903

Date: 7/25/2024



Southwest corner of location - Photo #03631



Northeast corner of location - Photo #03632

Inspection Photos

Location: Laramie Energy LLC CC/0605-01 Pad

Location ID: 323903

Date: 7/25/2024



Jul 25, 2024 at 11:47:51 AM
+39.556294,-108.247627 ±4.73m

Wildlife Hazard - Photo #03610



Jul 25, 2024 at 12:08:43 PM
+39.556310,-108.247676 ±4.72m

Wildlife Hazard - Photo #03626