

Inspection Photos

Location: Laramie Energy LLC CC/0605-13-22 Pad

Location ID: 324292

Date: 7/25/2024



Entrance to location - Photo #03639




Location - Photo #03646

Inspection Photos


Location: Laramie Energy LLC CC/0605-13-22 Pad

Location ID: 324292

Date: 7/25/2024



Wellhead - Photo #03640



Separator/Dehydrator - Photo #03642



Inspection Photos

Location: Laramie Energy LLC CC/0605-13-22 Pad

Location ID: 324292

Date: 7/25/2024



Tank battery - Photo #03645



Open ended load line - Photo #03651

Inspection Photos

Location: Laramie Energy LLC CC/0605-13-22 Pad

Location ID: 324292

Date: 7/25/2024



Southeast corner of location - Photo #03653



Southwest corner of location - Photo #03654

Inspection Photos

Location: Laramie Energy LLC CC/0605-13-22 Pad

Location ID: 324292

Date: 7/25/2024



Northeast corner of location - Photo #03655

