

## Inspection Photos

Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Entrance to location - Photo #03667




Location - Photo #03698

## Inspection Photos


Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Wellhead/Chemical tank - Photo #03668



Separator/Dehydrator - Photo #03678



## Inspection Photos

Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Tank battery - Photo #03696



Southeast corner of location - Photo #03704

## Inspection Photos

Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Southwest corner of location - Photo #03705



Northeast corner of location - Photo #03706



## Inspection Photos

Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Debris - Photo #03673



Debris - Photo #03675



## Inspection Photos

Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Debris - Photo #03676



Wildlife hazard - Photo #03684



## Inspection Photos

Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Wildlife hazard - Photo #03690



Debris - Photo #03693



## Inspection Photos

Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Wildlife hazard - Photo #03694



Open ended load line - Photo #03701



## Inspection Photos

Location: Laramie Energy LLC CC/0605-23 Pad

Location ID: 335802

Date: 7/25/2024



Open ended load line - Photo #03702

