


Inspection Photos

Location: Caerus Piceance LLC SG/E34 496
Location ID: 335928
Date: 7/26/2024



Entrance to location - Photo #03721

Location - Photo #03756

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Wellheads - Photo #03722



Wellheads - Photo #03723

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Wellheads - Photo #03724



Wellheads - Photo #03725

Inspection Photos
Location: Caerus Piceance LLC SG/E34 496
Location ID: 335928
Date: 7/26/2024



Wellhead - Photo #03726



Gas lift - Photo #03729

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Gas lift - Photo #03730



Gas lift - Photo #03731

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Gas lift - Photo #03732



Gas lift - Photo #03733

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Separator - Photo #03734



Separator - Photo #03735

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Separator - Photo #03736



Separators - Photo #03760

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Sales meters - Photo #03738



Sales meters - Photo #03739

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Tank battery - Photo #03753



Tank battery/No tank battery sign - Photo #03768

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Northeast corner of location - Photo #03796



Southside of location - Photo #03800

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Wildlife Hazard - Photo #03741



Wildlife Hazard - Photo #03742

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Wildlife Hazard - Photo #03744



Wildlife Hazard - Photo #03746

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Wildlife Hazard - Photo #03752



Wildlife Hazard - Photo #03794

Inspection Photos

Location: Caerus Piceance LLC SG/E34 496

Location ID: 335928

Date: 7/26/2024



Safety/Wildlife Hazard - Photo #03797



Stockpiled soils with no BMP's - Photo #03798