

# Inspection Photos

Loc: 478240

Operator: THOMAS L SPRING LLC

Inspection Date: 8/7/2024

County: Bent



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the JC #2 tank battery. There are undesirable weeds throughout the location that need to be controlled.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 478240 | Date: 8/7/2024



## Inspection Photos



**Photo 2.** Weeds around the equipment need to be removed. Sign is posted at meter shed.



## Inspection Photos



**Photo 3.** The secondary containment around the tank is insufficient to contain a spill .

