

Inspection Photos

API: 011-06083

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 8/7/2024

County: BENT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road. There is erosion along the road that must be repaired and stabilized.



Inspection Photos



Photo 2. Facing southeast toward the wellsite and tank battery. There is a dead cow carcass laying next to the tank!



Inspection Photos



Photo 3. There was an oil leak by the outlet. There is still stained soils that need to be cleaned up.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. There are holes in the berm which needs maintenance. Since the well is temporarily abandoned the tank needs to be removed.



Inspection Photos



Photo 5. Facing toward the well which is temporarily abandoned. Unused equipment needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-06083 | Date: 8/7/2024

Inspection Photos



Photo 6. Facing west at the location. There are areas of the location that are bare of vegetation that need to be reseeded.

