

Inspection Photos


Location: Laramie Energy LLC CC/604-41-32 Pad

Location ID: 335902

Date: 8/2/2024



Entrance to location - Photo #04009



Location - Photo #04032

Inspection Photos

Location: Laramie Energy LLC CC/604-41-32 Pad

Location ID: 335902

Date: 8/2/2024



Wellheads - Photo #04011



Separators - Photo #04016

Inspection Photos

Location: Laramie Energy LLC CC/604-41-32 Pad

Location ID: 335902

Date: 8/2/2024



Separators - Photo #04017



Separators - Photo #04018



Inspection Photos

Location: Laramie Energy LLC CC/604-41-32 Pad

Location ID: 335902

Date: 8/2/2024



Aug 2, 2024 at 2:06:07 PM
+39.557165,-108.218845 ±4.73m
De Beque

Separators - Photo #04019



Aug 2, 2024 at 2:13:00 PM
+39.557014,-108.218352 ±4.76m
De Beque

Tank battery - Photo #04026

Inspection Photos

Location: Laramie Energy LLC CC/604-41-32 Pad

Location ID: 335902

Date: 8/2/2024



Southwest corner of location - Photo #04054



Northwest corner of location - Photo #04055

Inspection Photos

Location: Laramie Energy LLC CC/604-41-32 Pad

Location ID: 335902

Date: 8/2/2024



Debris - Photo #04021



Debris - Photo #04047

Inspection Photos
Location: Laramie Energy LLC CC/604-41-32 Pad
Location ID: 335902
Date: 8/2/2024



Debris - Photo #04048



Debris - Photo #04049

Inspection Photos

Location: Laramie Energy LLC CC/604-41-32 Pad

Location ID: 335902

Date: 8/2/2024



Debris - Photo #04050



Debris - Photo #04051