


**Inspection Photos**  
**Location Name: Wallach 1-8H**  
**Location ID: 431888**



**Photo 1 – Wellhead**



**Photo 2 – Well Sign**

**Inspection Photos**  
**Location Name: Wallach 1-8H**  
**Location ID: 431888**



**Photo 3 – Heater Treater**



**Photo 4 – Gas Meter**



**Inspection Photos**  
**Location Name: Wallach 1-8H**  
**Location ID: 431888**



**Photo 5 – Tank Battery**



**Photo 6 – Flare and ECD**

**Inspection Photos**  
**Location Name: Wallach 1-8H**  
**Location ID: 431888**



**Photo 7 – Sales Line closed upstream of Meter**



**Photo 8 – Buy Back Meter**



**Inspection Photos**  
**Location Name: Wallach 1-8H**  
**Location ID: 431888**



**Photo 9 – Flare Meter**



**Photo 10 – Today Total**



Inspection Photos  
Location Name: Wallach 1-8H  
Location ID: 431888




**Photo 11 – Yesterday Total – 8.2 MCF**



**Photo 12 – Flare Gas Meter – Flow Rate**

**Inspection Photos**  
**Location Name: Wallach 1-8H**  
**Location ID: 431888**



**Photo 13 – Flare Meter**




**Photo 14 – Flare**



**Inspection Photos**  
**Location Name: Wallach 1-8H**  
**Location ID: 431888**



**Photo 15 – Flare Valve Open on Flare Line**



**Photo 16 – Tank Battery**



Inspection Photos  
Location Name: Wallach 1-8H  
Location ID: 431888



Energy and Carbon Management Commission  
40.59206, -104.24037, 4884.2ft  
07/23/2024 13:48:30

Photo 17 – Tank Battery Sign



Energy and Carbon Management Commission  
40.59222, -104.24009, 4911.6ft  
07/23/2024 13:50:23

Photo 18 – Buy-Back Calibration Card

Inspection Photos  
Location Name: Wallach 1-8H  
Location ID: 431888



Photo 19 – Sales Meter Calibration Card