

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 1 – Wellhead



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 3 – Tank Battery



Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891




Photo 5 – Gas Sales Meter




Photo 6 – Sales Line valve in the closed position

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Energy and Carbon Management Commission
 40.59672, -104.31974, 4818.8ft
 07/23/2024 14:11:02



Energy and Carbon Management Commission
 40.59672, -104.31974, 4818.1ft
 07/23/2024 14:11:24

Photo 7 – Sales Line

Photo 8 – Sales Meter Calibration Card

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 9 – Flare Meter



Photo 10 – Flow Rate

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891




Photo 11 – Today Total

Photo 12 – Yesterday Total

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 13 – ECD



Photo 14 – Flare

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 15 – Flare Valve Open on Flare Line



Photo 16 – Pilot Supply Valve in closed position