

**Inspection Photos**  
**Location Name: Planck 1-14H**  
**Location ID: 424707**



**Photo 1 – Tank Battery**



**Photo 2 – Well Sign**

**Inspection Photos**  
**Location Name: Planck 1-14H**  
**Location ID: 424707**



**Photo 3 – Wellhead – Stained Soil**




**Photo 4 – Stained Soil**



**Inspection Photos**  
**Location Name: Planck 1-14H**  
**Location ID: 424707**



**Photo 5 – Sales Line Valves in open position**




**Photo 6 – Sales Line Valves in open position**



**Inspection Photos**  
**Location Name: Planck 1-14H**  
**Location ID: 424707**



**Photo 7 – Sales Line Valves in open position**



**Photo 8 – Static Pressure**



**Inspection Photos**  
**Location Name: Planck 1-14H**  
**Location ID: 424707**



**Photo 9 – Flow Rate**



**Photo 10 – Yesterday Volume**

**Inspection Photos**  
**Location Name: Planck 1-14H**  
**Location ID: 424707**



**Photo 11 – ECD and Combustor**



**Photo 12 – Valves in Open position and Pilot Light on**



Inspection Photos  
Location Name: Planck 1-14H  
Location ID: 424707



Energy and Carbon Management Commission  
40.66783, -104.2792, 5011.9ft  
07/23/2024 14:48:43

**Photo 13 – Flare Gas Meter – Today Volume – 15.48 MCF**



Energy and Carbon Management Commission  
40.66782, -104.2792, 5027.0ft  
07/23/2024 14:48:47

**Photo 14 – Flare Gas Meter – Yesterday Volume – 37.7 MCF**

**Inspection Photos**  
**Location Name: Planck 1-14H**  
**Location ID: 424707**



**Photo 15 – Tank Battery**



**Photo 16 – Tank Battery Sign**