

Inspection Photos  
Location Name: Wickstrom 18-2H  
Location ID: 433082



Energy and Carbon Management Commission  
40.49449, -104.14117, 4622.3ft  
07/24/2024 12:20:52



Energy and Carbon Management Commission  
40.4945, -104.1412, 4644.5ft  
07/24/2024 12:20:56

Photo 1 – Tank Battery

Photo 2 – Tank Battery Sign

**Inspection Photos**  
**Location Name: Wickstrom 18-2H**  
**Location ID: 433082**



**Photo 3 – Heater Treater and Propane Tank**



**Photo 4 – Gas Meter**

**Inspection Photos**  
**Location Name: Wickstrom 18-2H**  
**Location ID: 433082**




**Photo 5 – Sales Line Valves appear to be in open position**



**Photo 6 – Sales Line Valves appear to be in open position**

**Inspection Photos**  
**Location Name: Wickstrom 18-2H**  
**Location ID: 433082**



Energy and Carbon Management Commission  
 40.49449, -104.14182, 4648.7ft  
 07/24/2024 12:22:34



Energy and Carbon Management Commission  
 40.49449, -104.14181, 4651.4ft  
 07/24/2024 12:23:04

**Photo 7 – Sales Meter Calibration Card**

**Photo 8 – Flow Rate**

**Inspection Photos**  
**Location Name: Wickstrom 18-2H**  
**Location ID: 433082**



**Photo 9 – Yesterday Volume**

**Photo 10 – Accum. Volume**

**Inspection Photos**  
**Location Name: Wickstrom 18-2H**  
**Location ID: 433082**



**Photo 11 – Flare and ECD**



**Photo 12 – Flare Gas Meter – Valves appear to be in Open position to Flare Line**

Inspection Photos  
Location Name: Wickstrom 18-2H  
Location ID: 433082



Photo 13 – Today Total




Photo 14 – Yesterday Total

**Inspection Photos**  
**Location Name: Wickstrom 18-2H**  
**Location ID: 433082**



**Photo 15 – Pilot to Flare appears to be in the Closed Position**



**Photo 16 – Valve to ECD appears to be in Open Position**

Inspection Photos  
Location Name: Wickstrom 18-2H  
Location ID: 433082



Energy and Carbon Management Commission  
40.49456, -104.14173, 4649.0ft  
07/24/2024 12:27:46



Energy and Carbon Management Commission  
40.49486, -104.14165, 4647.8ft  
07/24/2024 12:28:00

Photo 17 – Pumping Unit

Photo 18 – Well Sign

Inspection Photos  
Location Name: Wickstrom 18-2H  
Location ID: 433082



Photo 19 – Wellhead



Photo 20 – Sign at Entrance