

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 3 – Well Sign



Photo 4 – Electric Motor

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 5 – ECD and Flare




Photo 6 – Flare Line Valves appear to be in open position

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 7 – Pilot Valve appears to be in closed position



Photo 8 – ECD

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 9 – Today Total




Photo 10 – Yesterday Volume

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 11 – Flare Gas Meter



Photo 12 – Heater Treater

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441





Photo 13 – Sales Line appears to be in closed position Upstream of Meter



Photo 14 – Gas Sales Meter

Location ID: 428441



Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 17 – Flow Rate



Photo 18 – Yesterday Volume

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 19 – Tank Battery



Photo 20 – Tank Battery

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 21 – Sign at Entrance