

Inspection Photos

August 6th, 2024

Operator: Simcoe LLC - 10749

Location ID: 311975

Inspection Document #: 714001054

La Plata County, CO

Township: SENW 23 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Linder 23-01 1R, 2, 3, 4
Location ID: 311975

8/6/24
+37.176739,-107.800327
35° NE



Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Linder 23-01 1R, 2, 3, 4
Location ID: 311975

8/6/24
+37.176797,-107.800527
222° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Patches of flowering Musk thistle observed throughout the location.

API #: 067-08965

Inspection Photos
Location Name: Linder 23-01 1R, 2, 3, 4
Location ID: 311975

8/6/24
+37.177115,-107.799486
303° NW



Inspection Photos

Location Name: Linder 23-01 1R, 2, 3, 4

Location ID: 311975



8/6/24
+37.176691,-107.799429
156° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of Pine, Sagebrush and Broom snakeweed.

API #: 067-08965