

# Inspection Photos

August 6th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334265

Inspection Document #: 714001055

La Plata County, CO

Township: SWNE 13 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources





Inspection Photos  
Location Name: Fassett 02-13 1  
Location ID: 334265



**Photo 2.** Patches of flowering Musk and Canada thistle observed throughout the active disturbance.



Inspection Photos  
Location Name: Fassett 02-13 1  
Location ID: 334265




**Photo 3.** Produced water tank placard/label is damaged and illegible.



Inspection Photos  
Location Name: Fassett 02-13 1  
Location ID: 334265



8/6/24  
+37.193629,-107.772990  
143° SE



8/6/24  
+37.192876,-107.772740  
161° S

**Photo 4.** View of additional patches of flowering Musk and Canada thistle observed along the fringes of the access road.



Inspection Photos  
Location Name: Fassett 02-13 1  
Location ID: 334265

8/6/24  
+37.193726,-107.773969  
202° S



**Photo 5.** Grass agriculture field reference area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06785