

Inspection Photos

August 6th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333703

Inspection Document #: 714001058

La Plata County, CO

Township: NESW 9 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ralph A2, A4
Location ID: 333703



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Storm water corrective action identified in the previous inspection doc #714000278 has been addressed/resolved.

API #: 067-08499, 09236

Inspection Photos
Location Name: Ralph A2, A4
Location ID: 333703



Photo 3. View of flowering Musk thistle and Tamarisk observed in the northwestern portion of the disturbance.

Inspection Photos
Location Name: Ralph A2, A4
Location ID: 333703

8/6/24
+37.202200,-107.726394
250° W



Photo 4. View of the southern interim reclamation area facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08499, 09236